






Address:	
Inspection Date:	June 01, 2021
Company:	O'Neil Consulting
Contact:	
Certified Thermographer:	Matt O'Neil
Valid Certification Number:	CDN-2020314
Infrared Camera Used:	Mavic 2 Enterprise Dual
Date of last calibration:	April 01 2021




Inspection

This Infrared Thermography Inspection report provides complete documentation of the thermal patterns detected in your equipment, structures or systems. We use an objective evaluation to help you prioritize repairs to provide the maximum return for this Inspection and its Maintenance Program based on IR Thermography.




North roof section, anomaly found in the SE corner of this section could be due to a build up of granules in the corner holding the heat longer than the rest of the system. Also, possible wet area found south of the roof top unit, this could also be debris from ponding water, invasive test will be needed to confirm moisture in the system.







The center section has an anomaly on the east side of the roof, possibly water infiltrating from the roof top unit or the heat duct. Invasive test will be needed to confirm moisture in the system.






Close up of center section over anomaly





The south section of roof I have found the biggest anomaly, water seems to be infiltrating the system from the roof top unit on the west side of the building. Invasive test will be needed to confirm moisture in the system.





Overview of all sections





Thermal



June 02, 2021

Attending Inspector Name:

Matt O'Neil

Certified Thermographer.

Signature: